




## PHAP13-00015

**Date:** August 5, 2013  
**Application Type:** Certificate of Appropriateness  
**Property Owner:** Carlos and Yadira Rubio  
**Representative:** Jose Lozano  
**Legal Description:** Being 10 Sunset Heights 30 & W 1/2 of 29, Texas, El Paso County, Texas.  
**Historic District:** Sunset Heights  
**Location:** 620 Prospect Street  
**Representative District:** #8  
**Existing Zoning:** A-2/H (Apartments/Historic)  
**Year Built:** 1921  
**Historic Status:** Contributing  
**Request:** Certificate of Appropriateness for the replacement of sash, wood, multi-light windows with fixed metal windows after-the-fact.  
**Application Filed:** 07/24/2013  
**45 Day Expiration:** 09/07/2013

## ITEM #1



**GENERAL INFORMATION:**

The applicant seeks approval for:

Certificate of Appropriateness for the replacement of sash, wood, multi-light windows with fixed metal windows after-the-fact.

**STAFF RECOMMENDATION:**

- The Historic Preservation Office recommends DENIAL of the proposed scope of work based on the following recommendations:

*The Design Guidelines for El Paso's Historic Districts, Sites, and Properties* recommend the following:


- *If windows are damaged beyond repair, replacement windows should match the type (such as double hung), style (for example six panes over six panes), and finish (paint).*
- *Replacement windows on the main façade shall be comprised of the operable portions of the window and match the type, style, operation, configuration and finish of the original windows.*
- *Do not use single pane picture windows or horizontal sliding windows if they are not the original window types.*
- *Installation of windows similar to the original in appearance and structural purpose, regardless of construction materials is permitted.*

*The Secretary of the Interior's Standards for Rehabilitation* recommend the following:


- *The historic character of a property will be retained and preserved. The removal of distinctive materials or alterations of features, spaces, and spatial relationships that characterize a property will be avoided.*

## AERIAL MAP

PHAP13-00015



# ELEVATION AND WINDOW SECTION



NOTE; Propose to change all exiting wood windows with metal windows to resemble wood and for all Windows to be consistent with original design, Today all windows are not consistent;  
The top 6 windows are not consistent:  
The 3 left windows are 6 over 4, the 3 right windows and the center window are 6 over 1.  
The right bottom window is 6 over 6 and the left window is 1 over 1.  
We will replace all top windows with 9 over 9 and the center top window and side windows 6 over 6.  
The 7 top windows **will not open** due to safety and because of a refrigerated air on top floor and the bottom and side windows will open as original design, all 6 over 6, **all will look as original built.**

\*Color on brick will remain the same, wood and window frame & trims will be painted as per exhibit A  
All wood trimming and design will remain original as built and rematch and painted as per exhibit A

